# MOTOR AGE INDEX

### OF 1945 FEATURES

AXLES . WHEEL ALIGNMENT . BODY REPAIRS . BRAKES . ELECTRICAL SERVICE

AXLES AND WHEEL ALIGNMENT Aligns 30 Jobs Per Day	Page 32 Page 29 Page 28	Advertising Sells July, Selling Super Service Aug., Lubricating the 1945 Ford Commercial Sept., Lube Jobs Boost Service Volume Nov., 1946 Pontiac Lubrication Dec.,	Page 24 Page 28 Page 30 Page 38 Page 26
		1940 Fundac Educación	7 00 000
BODY, SERVICE AND PAINTING			
Windshield Sealing Procedure, 1942 BuickJan.,	Page 40	MECHANICS TRAINING Trouble Shooting on Automatic TransmissionsJan.,	Page 26
Back Window Sealing Procedure, 1942 BuickFeb.,	Page 40	Solving Wrist Pin RiddlesFeb.,	Page 24
Recementing WeatherstripApril, Replacing Ford 1946 Windshield GlassNov.,	Page 28	Fuel Lines Frozen	Page 24
Replacing 1946 Ford Rear Window ReplacementDec.,	Page 22	Reducing SludgeMar.,	Page 26
		Hudson Vacumatic Drive ServiceApril,	
		Why Universal Joints Run DryApril, Truck Front Axle Alignment SpecificationsApril,	Page 24 Page 29
BODY, DOOR LATCHES Servicing General Motors Door LatchesJuly,	Page 23	Replacing Cadillac CrankshaftApril,	Page 94
Servicing Door LatchesAug.,	Page 44	Disassembling GMC Shift ControlApril,	Page 94
		Slipping Out of Automatic Clutch TroubleMay,	Page 24
BRAKE SERVICE		Too Fast For ReverseJune, Servicing Transmission ShiftersJuly,	Page 24 Page 30
Overhauling Air Brake CompressorsJan.,	Page 20	Stopping Brake GrabJuly,	Page 30
Servicing Air BrakesFeb.,	Page 26	Pointers on Installing PointsAug.,	Page 24
Air Brake Maintenance	Page 26	You Can't Fool With Fuel Lines Aug.,	
Causes and Cure For Low Brake Pedal on Hydraulic BrakesJune,	Page 32	Servicing Chrysler Column ShiftersAug., Putting the Heat on Carburetor TroubleSept.,	Page 30 Page 26
Stopping Brake GrabJuly,	Page 30	Servicing the Timken "D.P." BrakeOct.,	Page 24
Servicing 1945 Ford Truck BrakesAug.,	Page 25	Timing Valves for Better PerformanceOct.,	Page 26
Servicing the Timken "D.P." BrakeOct.,	Page 23	Keeping Cool When Engines OverheatNov., Replacing Ford 1946 Windshield GlassNov.,	Page 26 Page 27
National Inspection of BrakesMar.,	Page 29	Servicing Electric Windshield WipersNov.,	Page 40
		What Price Chains	Page 28
CARBURETOR SERVICE Fuel Lines FrozenMar.,			
Car Dealer Emphasizes Carburetor Tune-upJune,	Page 24 Page 26	MISCELLANEOUS	
Putting the Heat on Carburetor TroubleSept	Page 26	Fast Profitable Postwar ServiceJan.,	Page 23
You Can't Fool with Fuel LinesAug.,		New Bearings for Heavy DutyJan.,	Page 28
		Cleaning Engines with DetergentsFeb., British Develop New Rotary ValveFeb.,	Page 20 Page 22
CLUTCH SERVICE		Surveying the Postwar MarketFeb.,	Page 28
Slipping Out of Automatic Clutch TroubleMay,	Page 24	Triptane, a Super FuelFeb.,	Page 31
		Fuel Injection Boosts PowerFeb.,	Page 32
COOLING SYSTEM SERVICE		Developing PersonalityFeb., Expansion Built on Tune-upMar.	Page 60 Page 20
Don't Let Radiators Rust!	Page 28	Higher Wages Bring ProfitsMar.,	Page 23
Tractor Cooling Systems, Massey-HarrisMay,	Page 40	Battery Scarcity LoomsMar.,	Page 46
Keeping Cool When Engines OverheatNov.,	Page 26	How the Army Rebuilds Them	
		Why Universal Joints Run Dry	Page 100
ELECTRICAL SERVICE		Alcohol Water Injection	Page 20
Body Wiring Diagram, 1942 Buick, Series 41Jan., Body Wiring Diagram, 1942 Buick, Series 41-SEFeb.,	Page 39 Page 38	Dealers Alert! New Cars Are ComingJune,	Page 21
Body Wiring Diagram, 1942 Buick, Model 44April,		Dealers Protest OPA's Regulation on Time LimitsJune, Check of Wartime Gas Shows Marked ChangesJune,	Page 32 Page 88
Body Wiring Diagram, 1942 Buick, Model 47July,	Page 38	Servicemen Protest OPA Service SchedulesJuly,	Page 24
Body Wiring Diagram, 1942 Buick, Models 48, 48-S. Nov.,	Page 52	Advertising SellsAug.,	Page 22
Body Wiring Diagram, 1942 Buick, Models 51-71Dec., Regulator Test DataJan.,	Page 44 Page 24	C.I.O. Trying to Organize MechanicsJuly,	Page 26
Regulator Test DataFeb.,	Page 30	Bearing Facts About Ball BearingsJuly, Job Opportunities in Automotive Field for Veterans. July,	Page 32 Page 54
Pointers On Installing Points	Page 24	Tips on How to Buy Surplus PropertyJuly.	Page 56
Servicing Electric Windshield Wipers Nov.,	Page 38	OPA Lays an EggAug.,	Page 21
		Kaiser Enters Auto Field	Page 21
ENGINE SERVICE		OPA Boosts RateSept.,	
Cleaning Engines with Detergents Jan.,	Page 20	Will Torsion Bars Replace Coil and Leaf Springs? Sept	Page 28
Solving Wrist Pin RiddlesFeb.,	Page 24	Some Light On Glare Sent.	Page 32
Fuel Lines Frozen Mar., Reducing Sludge Mar.,	Daves 96	Number of Mechanics IncreasingDec., NADA Raps OPADec.,	Page 28
Replacing Cadillac Crankshafts	Page 94	GM Strike Outcome May Set Pattern for Industry Dec.	Page 27
Keep Gases Out of the Car May	Page 22	Only Slight Drop in Car Registrations Dec	Page 27
More Power From Better Valves	Page 28 Page 21	What Makes a Torsion Bar Spring? Dec.	Page 58
Tuning Engines to Prewar Standards Sept.	Page 24	Dealer Triples Service BusinessDec.,	Page 37
Timing Valves for Better PerformanceOct.,	Page 26	NEW BEVELORMENTS	
Causes and Cure of Piston LacqueringDec.,	Page 38	NEW DEVELOPMENTS  New Bearings for Heavy DutyJan.,	Do 00
		British Develop New Rotary Valve Feb.	Page 28 Page 22
LUBRICATION		Triptane, a Super Fuel Fob	Page 31
When Universal Joints Run Dry	Page 24	Fuel Injection Boosts Power Feb	Page 32
Accent On Lubrication	Page 31 Page 23	Alcohol Water Injection	Page 20
May,	1 480 23	(Commune on page 52)	

# MOTOR AGE INDEX

### OF 1945 FEATURES

AXLES . WHEEL ALIGNMENT . BODY REPAIRS . BRAKES . ELECTRICAL SERVICE

AXLES AND WHEEL ALIGNMENT Aligns 30 Jobs Per Day	Page 32 Page 29 Page 28	Advertising Sells July, Selling Super Service Aug., Lubricating the 1945 Ford Commercial Sept., Lube Jobs Boost Service Volume Nov., 1946 Pontiac Lubrication Dec.,	Page 24 Page 28 Page 30 Page 38 Page 26
		1940 Fundac Educación	7 00 000
BODY, SERVICE AND PAINTING			
Windshield Sealing Procedure, 1942 BuickJan.,	Page 40	MECHANICS TRAINING Trouble Shooting on Automatic TransmissionsJan.,	Page 26
Back Window Sealing Procedure, 1942 BuickFeb.,	Page 40	Solving Wrist Pin RiddlesFeb.,	Page 24
Recementing WeatherstripApril, Replacing Ford 1946 Windshield GlassNov.,	Page 28	Fuel Lines Frozen	Page 24
Replacing 1946 Ford Rear Window ReplacementDec.,	Page 22	Reducing SludgeMar.,	Page 26
		Hudson Vacumatic Drive ServiceApril,	
		Why Universal Joints Run DryApril, Truck Front Axle Alignment SpecificationsApril,	Page 24 Page 29
BODY, DOOR LATCHES Servicing General Motors Door LatchesJuly,	Page 23	Replacing Cadillac CrankshaftApril,	Page 94
Servicing Door LatchesAug.,	Page 44	Disassembling GMC Shift ControlApril,	Page 94
		Slipping Out of Automatic Clutch TroubleMay,	Page 24
BRAKE SERVICE		Too Fast For ReverseJune, Servicing Transmission ShiftersJuly,	Page 24 Page 30
Overhauling Air Brake CompressorsJan.,	Page 20	Stopping Brake GrabJuly,	Page 30
Servicing Air BrakesFeb.,	Page 26	Pointers on Installing PointsAug.,	Page 24
Air Brake Maintenance	Page 26	You Can't Fool With Fuel Lines Aug.,	
Causes and Cure For Low Brake Pedal on Hydraulic BrakesJune,	Page 32	Servicing Chrysler Column ShiftersAug., Putting the Heat on Carburetor TroubleSept.,	Page 30 Page 26
Stopping Brake GrabJuly,	Page 30	Servicing the Timken "D.P." BrakeOct.,	Page 24
Servicing 1945 Ford Truck BrakesAug.,	Page 25	Timing Valves for Better PerformanceOct.,	Page 26
Servicing the Timken "D.P." BrakeOct.,	Page 23	Keeping Cool When Engines OverheatNov., Replacing Ford 1946 Windshield GlassNov.,	Page 26 Page 27
National Inspection of BrakesMar.,	Page 29	Servicing Electric Windshield WipersNov.,	Page 40
		What Price Chains	Page 28
CARBURETOR SERVICE Fuel Lines FrozenMar.,			
Car Dealer Emphasizes Carburetor Tune-upJune,	Page 24 Page 26	MISCELLANEOUS	
Putting the Heat on Carburetor TroubleSept	Page 26	Fast Profitable Postwar ServiceJan.,	Page 23
You Can't Fool with Fuel LinesAug.,		New Bearings for Heavy DutyJan.,	Page 28
		Cleaning Engines with DetergentsFeb., British Develop New Rotary ValveFeb.,	Page 20 Page 22
CLUTCH SERVICE		Surveying the Postwar MarketFeb.,	Page 28
Slipping Out of Automatic Clutch TroubleMay,	Page 24	Triptane, a Super FuelFeb.,	Page 31
		Fuel Injection Boosts PowerFeb.,	Page 32
COOLING SYSTEM SERVICE		Developing PersonalityFeb., Expansion Built on Tune-upMar.	Page 60 Page 20
Don't Let Radiators Rust!	Page 28	Higher Wages Bring ProfitsMar.,	Page 23
Tractor Cooling Systems, Massey-HarrisMay,	Page 40	Battery Scarcity LoomsMar.,	Page 46
Keeping Cool When Engines OverheatNov.,	Page 26	How the Army Rebuilds Them	
		Why Universal Joints Run Dry	Page 100
ELECTRICAL SERVICE		Alcohol Water Injection	Page 20
Body Wiring Diagram, 1942 Buick, Series 41Jan., Body Wiring Diagram, 1942 Buick, Series 41-SEFeb.,	Page 39 Page 38	Dealers Alert! New Cars Are ComingJune,	Page 21
Body Wiring Diagram, 1942 Buick, Model 44April,		Dealers Protest OPA's Regulation on Time LimitsJune, Check of Wartime Gas Shows Marked ChangesJune,	Page 32 Page 88
Body Wiring Diagram, 1942 Buick, Model 47July,	Page 38	Servicemen Protest OPA Service SchedulesJuly,	Page 24
Body Wiring Diagram, 1942 Buick, Models 48, 48-S. Nov.,	Page 52	Advertising SellsAug.,	Page 22
Body Wiring Diagram, 1942 Buick, Models 51-71Dec., Regulator Test DataJan.,	Page 44 Page 24	C.I.O. Trying to Organize MechanicsJuly,	Page 26
Regulator Test DataFeb.,	Page 30	Bearing Facts About Ball BearingsJuly, Job Opportunities in Automotive Field for Veterans. July,	Page 32 Page 54
Pointers On Installing Points	Page 24	Tips on How to Buy Surplus PropertyJuly.	Page 56
Servicing Electric Windshield Wipers Nov.,	Page 38	OPA Lays an EggAug.,	Page 21
		Kaiser Enters Auto Field	Page 21
ENGINE SERVICE		OPA Boosts RateSept.,	
Cleaning Engines with Detergents Jan.,	Page 20	Will Torsion Bars Replace Coil and Leaf Springs? Sept	Page 28
Solving Wrist Pin RiddlesFeb.,	Page 24	Some Light On Glare Sent.	Page 32
Fuel Lines Frozen Mar., Reducing Sludge Mar.,	Daves 96	Number of Mechanics IncreasingDec., NADA Raps OPADec.,	Page 28
Replacing Cadillac Crankshafts	Page 94	GM Strike Outcome May Set Pattern for Industry Dec.	Page 27
Keep Gases Out of the Car May	Page 22	Only Slight Drop in Car Registrations Dec	Page 27
More Power From Better Valves	Page 28 Page 21	What Makes a Torsion Bar Spring? Dec.	Page 58
Tuning Engines to Prewar Standards Sept.	Page 24	Dealer Triples Service BusinessDec.,	Page 37
Timing Valves for Better PerformanceOct.,	Page 26	NEW BEVELORMENTS	
Causes and Cure of Piston LacqueringDec.,	Page 38	NEW DEVELOPMENTS  New Bearings for Heavy DutyJan.,	Do 00
		British Develop New Rotary Valve Feb.	Page 28 Page 22
LUBRICATION		Triptane, a Super Fuel Fob	Page 31
When Universal Joints Run Dry	Page 24	Fuel Injection Boosts Power Feb	Page 32
Accent On Lubrication	Page 31 Page 23	Alcohol Water Injection	Page 20
May,	1 480 23	(Commune on page 52)	

### MOTOR AGE INDEX

#### OF 1945 FEATURES

ENGINE SERVICE . LUBRICATION . SUPER SERVICE . TRUCKS . TUNE-UP

(Canthonal from mans AC)		T0.40T0.000	
(Continued from page 46)		TRACTORS	Page 40
Gas Turbine Possibilities in Motor Trucks May,	Page 30	Tractor Cooling SystemMay, Allis Chalmers Tractor TransmissionJune,	Page 40
Will Two-way Radio Speed Repair Jobs?June,	Page 22	Selling Tractors To Save SoilSept.,	Page 22
New Turbosupercharger Described at MeetingJune,	Page 94	Sening Tractors to Dave Don	
Some Light on GlareSept.,	Page 32		
Heating the Postwar ShopOct.,	Page 20	TRANSMISSION SERVICE	
	Page 114	Trouble Shooting on Automatic TransmissionsJan.,	Page 26
Jet Propulsion Developments Dec.,	Page 56	Hudson Vacumatic Drive ServiceMar.,	Page 30
New Engines Reflect War Improvements Dec.,	Page 24	When Universal Joints Run DryApril,	Page 24
		Too Fast For ReverseJune,	Page 24
POSTWAR CARS		Servicing Transmission ShiftersJune,	Page 30
POSTWAR CARS Ford, 1946July,	Page 25	Servicing Chrysler Column Shifters	Page 30
Nash, 1946July		Servicing Pontiac Safety Gear ShiftOct.,	Page 24
Packard, 1946July.	Page 25 Page 25		
Civilian Jeep AnnouncedAug.,	Page 20	TRUCKS	
New Oldsmobile Announced	Page 46	Keeping Truck Fleets RollingJan.,	Page 23
Details of the New Nash		Truck Front Axle Alignment SpecificationsApril,	Page 29
Oldsmobile Plans 3 Basic 1946 ModelsSept.,		Disassembly GMC Shift ControlApril,	Page 94
Studebaker Sets October Production Date Sept		Keeping 'em Rolling	Page 26
1946 Hudson Models Due off Assembly LineSept.,	Page 80	Gas Turbine Possibilities in Motor TrucksMay,	Page 30
Buick Introduces 1946 ModelsOct.,	Page 28	Reo Filling Truck, Tractor NeedsJune,	Page 86
Cadillac Presents 1946 CarsOct.,	Page 30	Details on Ford Truck Models 59C and 59TJune,	Page 104
New Appearance Features 1946 HudsonOct.,	Page 31	Servicing 1945 Ford Truck BrakesAug.,	Page 25
New Pontiac Models AnnouncedOct.,	Page 32	Lubricating the 1945 Ford CommercialSept.,	Page 30
New Styling on Studebaker Oct.,	Page 37		
Chevrolet Announces New ModelsNov.,	Page 20		
New Packard Models IntroducedNov.,	Page 24	TUNE-UP	Dam- 09
		Tune-up for Lower Octane Fuels	Page 28
		More Power from Better Valves	Page 26
LETTERS TO THE EDITOR		Car Dealer Emphasizes Carburetor Tune-upJune, Tuning Engines to Prewar StandardsSept.,	Page 24
See Readers' Clearing House		Tuning Valves for Better PerformanceOct.,	Page 26
		Tuning valves for Better Performance	I age 20
*******			
SALVAGE		WAR-TIME REGULATIONS AND RATIONING	
How the Army Rebuilds ThemApril,		Experimental Model Work RestrictedJan.,	Page 70
Keeping 'em Rolling	Page 26	Army Tire CeilingsJan.,	Page 76
		10-ton Jack PricesJan.,	Page 76
		G. I. Loan RulesJan.,	Page 52
SELLING SERVICE	_	Ceiling Price Set on Used Assemblies Mar.,	Page 76
Loan Cars Boost Dealers' ServiceJan.,	Page 30	Says Time Charges Must Be DetailedApril,	Page 42
Developing PersonalityFeb.,	Page 60	Deadline Extended on Ration Coupon Accounts April,	Page 86
Expansion Built on Tune-up	Page 20	Tire Tube Control	Page 42
Aligns 30 Jobs Per Day	Page 52	Dealer Must Endorse Ration Coupon SheetsMay,	Page 42
They Sell Easy Riding		Reduce Wholesale Ceiling Price on SyntheticsMay,	Page 44
Accent On LubricationMay,	Page 23	Restrictions Removed on Replacement PartsJune,	Page 62
Car Dealer Emphasizes Carburetor Tune-upJune.	Page 31 Page 26	W.P.B. Revokes Handling Stored Vehicle OrdersJune,	Page 64
Advertising SellsJuly,	Page 24	Used 1942 Car Rationing LiftedJuly,	Page 98
Selling Wheel Alignment July	Page 28	Used Car Celling Price ReducedJuly,	
Selling Super Service	Page 28	Repair Time Regulation Postponed to September Aug.,	
Selling Tractors to Save Soil	Page 22	W.P.B. Removes Ban on Maintenance Equipment. Aug.,	Page 70
Selling Service By Direct Mail	Page 22	O.P.A. Announces Price Ceiling on Jeep	Page 80 Page 48
Gigantic Jobber Covers Mid-west Area	Page 30	W.P.B. Removes Production Ceilings on New Cars., Sept.,	
Dealer Triples Service BusinessDec.,	Page 37	Revocation of Wartime Controls AnnouncedSept.,	
		Truck-Trailer Rationing to End Dec. 1stOct.,	Page 80
		New Cars Off Rationing List	Page 56
SHOCK ABSORBERS		Used Car Sellers Must File Certificates	Page 56
They Sell Easy Riding	Page 23	Surplus Property Order on Vets Changed Nov.,	Page 56
		Ceiling Price on Lifts Announced Dec.,	Page 60
SHOP KINKS		Enforcement Division Organized for SPA Dec.,	Page 60
See Shop Kinks Section in each issue		Surplus Batteries Ceiling Price Announced Dec.,	Page 60
SUPER SERVICE			
		WHEEL ALIGNMENT	00
Expansion Built on Tune-up	Page 20	Aligns 30 Jobs Mar.,	
In Alignment with the Times	Page 22	Truck Front Axle Alignment Specifications April,	
Selling Super ServiceAug.,	Page 26	Selling Wheel AlignmentJuly,	Page 28
Lube Jobs Boost Service Volume	Page 38		
Tuning Engines to Pre-War StandardsSept.,	Dogo 94	WIRING DIAGRAM	
Pointers on Installing Points	Page 24	Body Wiring Diagram, 1942 Buick, Series 41Jan.,	Page 38
	1 age 24	Body Wiring Diagram, 1942 Buick, Series 41	Page 38
		Body Wiring Diagram, 1942 Buick, Model 44	
TIRES		Body Wiring Diagram, 1942 Buick, Model 47July,	Page 38
Keeping Truck Fleets Rolling Feb.,	Page 23	Body Wiring Diagram, 1942 Buick, Models 48, 48-S., Nov.,	
Profits from Tire Service	Page 30	Body Wiring Diagram, 1942 Buick, Models 51-71 Dec.,	Page 44

